



The best solution to measure your barrier film



New non-contact thickness measuring unit


KDvision-O/CNC

for measuring barrier films with
display of barrier distribution

► More than 20 systems successfully in operation

Expert in gauge measurement

New Visualisation with display of barrier distribution profile



Main advantages compared to other measuring devices:

- ▶ Very fast and direct measurement on the bubble, non-contact
- ▶ Highest precision, specifically also on barrier films <60µ
- ▶ Also suitable for all PE/PP films
- ▶ Measuring range 10-250µm
- ▶ Separate indication of barrier distribution profile, down to min. 1µ
- ▶ Very fast reaction time of gauge control system
- ▶ Scrap reduction, shorter change-over cycles
- ▶ No radiation, no licensing, no radiation officer
- ▶ No special protection walls necessary to block nuclear radiation

Expert in gauge measurement

